



## Round 6, Punta del Este (URY)

---

|             |                            |                     |            |
|-------------|----------------------------|---------------------|------------|
| <b>From</b> | The FIA Technical Delegate | <b>Document no.</b> | <b>62</b>  |
| <b>To</b>   | Stewards of the meeting    | <b>Date</b>         | 17/03/2018 |

---

### TECHNICAL DELEGATE'S REPORT No.11

---

#### RACE

Controls carried out after the race, are:

|  |                                  |
|--|----------------------------------|
| Weight and weight distribution                                 | Top 3 (both cars of each driver) |
| Tyres used, Camber, pressures & gas                            | Top 3 (both cars of each driver) |
| RESS, Emotor, gearbox used                                     | Top 3 (both cars of each driver) |
| Flame-resistant clothing (underwear)                           | Top 3 drivers                    |
| Bodywork elements (front wing, engine cover, Side pod LH & RH) | 2 car out of Top 3 cars          |

All the cars were found in compliance with the Regulations of the Championship with regards to the items checked.

---

#### ENERGY CONSUMPTION and POWER USAGE

No Report

**Time** 18:05  
Laurent Arnaud  
FIA Technical Delegate